



A	B	C 3.5*35	D 7*50	E	F 3*12	G	H 8*40	I 691MM
								
48PCS	48PCS	20PCS	10PCS	8PCS	10PCS	10PCS	12PCS	1PCS

1  1300*600 1PCS	2  460*120 2PCS	3  1208*120 2PCS	4  899*100 2PCS	5 899*65 2PCS
6  899*100 2PCS	7 899*65 2PCS	8  480*240 1PCS	9  480*240 1PCS	10  775*240 1PCS
11  775*240 1PCS	12  694*240 1PCS	13  305*223 1PCS	14  157*223 2PCS	15  703*155 2PCS
16 703*168 1PCS	17  297*220 2PCS	18  396*220 2PCS	19  312*220 2PCS	20  220*84 2PCS

Hardware installation demonstration

NOTE:Please make sure "A"hardware tightened and can't be pulled out!

I



II



III



①



	A*34	put A on board ① ④ ⑥

②



	A*14	put A on board ⑧ ⑩ ⑪

③



Make sure the arrow on the screw align to the hole on the side.

	B*20
	D*8

put B on board ⑤ ⑦

④





Make sure the arrow on the screw align to the hole on the side.

	B*14
	H*12

put B on board ② ③

⑤





Make sure the arrow on the screw align to the hole on the side.

	B*4
	D*2

put B on board ⑫ ⑬

⑥



Make sure the arrow on the screw align to the hole on the side.

	B*6
	I*1

put B on board ⑧ ⑨ ⑬

⑦



Make sure the arrow on the screw align to the hole on the side.

	B*4	put B on board ⑧ ⑨

8



	C*20

9



	E*8
	F*10
	G*10

⑩







END