




A x20
M15*12
+1(spare)



B x20
M6*40
+1(spare)




C x02
M6*15



D x08
M6*30
+1(spare)




E x04
M6*40
+1(spare)




F x04



G x28
M3*12



H x02




I x02



J x05




K x01




L x08

E x 2


K x 1




E x 2



D x 8




C x 2




J x 5

05




B x 8


06





B x 4



A x 4







B x 8

G x 4


H x 2



A x 8



L x 8



F x 4

G x 16

I x 2

