




①x1




②x1




③x1




④x1




⑤x1



⑥x1




⑦x1



Ax1



M6x25
Bx12




M6x40
Cx19



Ø10x10
Dx19



M4x20
Ex4




Fx2




M4x10
Gx28




Hx4




1




2




3




4




5




6




7




8




9



10



11



12

