





## Part list





## Hardware list **©**X8 BX8 **D**X12 $\bigcirc X1$ FX4 **E**)X33 ©X1 $\bigcirc$ X2 (L)X1 **K**X12 ()X2 $\bigcirc$ X4 **MX8**


































Put hardware M to the groove and tighten them with hardware E .





Fix hardware L1 to Part 1 with screw E.



Fix hardware L3 to the wall .

Fix hardware L2 to hardware L3 with hardware L1 .