













ASSEMBLY INSTRUCTION


END TABLE — CT0349




①  X1PC	②  X1PC	③  X1PC	④  X1PC	⑤  X4PCS
⑥  X4PCS	A  M6*12 X16PCS	B  X8PCS	C  X4PCS	D  X1PC




STEP1 :




STEP2 :




STEP3 :




STEP4 :



STEP5:



STEP6:



STEP7:

